

REPORT ON CONDITION OF SURVEY MARK

QUADRANGLE REPORT

STATE California COUNTY Inyo QUAD NAME Furnace Creek SW
 STATION NAME and/or NUMBER B 1907 -284 QUAD NUMBER 3611633 (324)
 LATITUDE _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
 LONGITUDE _____ " YEAR ESTABLISHED 1907 Line #1
 ELEVATION -275.133 ft/meter By USGS NGS OTHER _____ (Name of agency)
 CONDITION SFNF MARK STAMPED _____

REMARKS or REVISED DESCRIPTION: Due to vague description Bench Mark was not found.

SUBMITTED BY Ralph B. Findlay AGENCY U.S. Geological Survey DATE 04/28/83

Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. CSC-178

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE California COUNTY Inyo QUADRANGLE Furnace Creek 324
 QUOTE PRIMARY REFERENCE Furnace Creek Ranch, 5.9 mi. S.
 (Direction and distance) Line 1
 DESIGNATION { LISTED B 1907 -223
 STAMPED B 1907 -223 TYPE OF MARK: BM TT _____ TRIANG. _____

Lat. _____ " CONDITION Disturbed
 Long. _____ " Destroyed USGS USBR
 Elev. -224.129 feet Not Found USC&GS State GS
 USNPS USNFS
 USGLO (Other)
 USBLM

REMARKS OR REVISED DESCRIPTION: A thorough search was made in the area of the mark. The site is at the edge of the salt pan and all other marks at this elevation which were found were destroyed. I presume this mark has also been eaten off at the ground and been destroyed.

Please prepare in triplicate.

SUBMITTED BY Thomas T. Smith
 TITLE Cartographer DATE May 1, 1983
 AGENCY US Geological Survey

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE California COUNTY Inyo QUADRANGLE Furnace Creek 324
QUOTE PRIMARY REFERENCE Smith tank, 2.1 mi. n. of;
(Direction and distance)

DESIGNATION { LISTED B 1907 1330 TYPE OF MARK: BM X TT _____ TRIANG. _____
STAMPED B 1907 1330

Lat. _____' _____" CONDITION Disturbed
Long. _____' _____" Destroyed ESTABLISHED BY USGS USBR
Elev. 1329.761 feet Not Found USC&GS State GS
USNPS USNFS
USGLO (Other)
USBLM

REMARKS OR REVISED DESCRIPTION: The road has been changed. A through search was made at the site of the mark and nothing was found.

Please prepare in triplicate.

SUBMITTED BY Thomas W. Smith
TITLE Cartographer
AGENCY US Geological Survey

DATE May 1, 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE California COUNTY Inyo QUADRANGLE Furnace Creek 324
QUOTE PRIMARY REFERENCE Furnace Creek, 2.5 mi E. of;
(Direction and distance)

DESIGNATION { LISTED B 1907 283 TYPE OF MARK: BM X TT _____ TRIANG. _____
STAMPED B 1907 283

Lat. _____' _____" CONDITION Disturbed
Long. _____' _____" Destroyed ESTABLISHED BY USGS USBR
Elev. 282.505 feet Not Found USC&GS State GS
USNPS USNFS
USGLO (Other)
USBLM

REMARKS OR REVISED DESCRIPTION: A through search was made in the area of the mark and nothing was found.

Please prepare in triplicate.

SUBMITTED BY Thomas T. Smith
TITLE Cartographer
AGENCY US Geological Survey

DATE May 1, 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION