

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE Arizona COUNTY Maricopa QUADRANGLE Safford
QUOTE PRIMARY REFERENCE Safford, 1.5 mi. west of
(Direction and distance)

DESIGNATION { LISTED 2-14
STAMPED 2924.300 2-14 1932 TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
Disturbed ESTABLISHED BY
Long. _____ ° _____ ' _____ " Destroyed USGS USBR
Elev. 2924.300 feet Not Found USC&GS State GS
USNPS USNFS
USGLO } (Other)
USBLM }

REMARKS OR REVISED DESCRIPTION:

A search of the area was made of the area described, but the bench mark was not recovered. A considerable amount of construction work has been done on both the irrigation canal and the railroad in this area and it appears the bench mark has been destroyed.

SUBMITTED BY D. H. Grabel
TITLE Carto. rec.
AGENCY USGS

DATE March 1963

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE Arizona COUNTY Maricopa QUADRANGLE Safford
QUOTE PRIMARY REFERENCE Safford, 1.5 mi. west of
(Direction and distance)

DESIGNATION { LISTED 2-14
STAMPED 3080.600 TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
Disturbed ESTABLISHED BY
Long. _____ ° _____ ' _____ " Destroyed USGS USBR
Elev. 3080.600 feet Not Found USC&GS State GS
USNPS USNFS
USGLO } (Other)
USBLM }

REMARKS OR REVISED DESCRIPTION:

A considerable amount of earth has been removed from the area described to repair the erosion along the tracks and around the bridge. No trace of the bench mark was recovered and it is assumed it has been either destroyed or covered over.

SUBMITTED BY D. H. Grabel
TITLE Carto. rec.
AGENCY USGS

DATE March 1963

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE California COUNTY Orange QUADRANGLE 211 6000
 QUOTE PRIMARY REFERENCE 211 6000
 (Direction and distance)

DESIGNATION { LISTED ---
 STAMPED --- TYPE OF MARK: BM --- TT --- TRIANG. ---

Lat. 33° 55' 00" CONDITION Disturbed
 Long. 117° 55' 00" Destroyed ESTABLISHED BY USGS USBR
 Elev. 100 feet Not Found USC&GS State GS
 USNPS USNFS
 USGLO (Other)
 USBLM

REMARKS OR REVISED DESCRIPTION:

[Faint handwritten notes in the remarks section]

SUBMITTED BY --- DATE April 1965
 TITLE ---
 AGENCY ---

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE California COUNTY Orange QUADRANGLE 211 6000
 QUOTE PRIMARY REFERENCE 211 6000
 (Direction and distance)

DESIGNATION { LISTED ---
 STAMPED --- TYPE OF MARK: BM --- TT --- TRIANG. ---

Lat. 33° 55' 00" CONDITION Disturbed
 Long. 117° 55' 00" Destroyed ESTABLISHED BY USGS USBR
 Elev. 100 feet Not Found USC&GS State GS
 USNPS USNFS
 USGLO (Other)
 USBLM

REMARKS OR REVISED DESCRIPTION:

[Faint handwritten notes in the remarks section]

SUBMITTED BY --- DATE April 1965
 TITLE ---
 AGENCY ---

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE Arizona COUNTY Yuma QUADRANGLE 4000

QUOTE PRIMARY REFERENCE _____
(Direction and distance)

DESIGNATION { LISTED _____
STAMPED _____ TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
Long. _____ ° _____ ' _____ " Disturbed
Elev. _____ feet Destroyed ESTABLISHED BY
Not Found USGS USBR
USC&GS State GS
USNPS USNFS
USGLO } (Other)
USBLM }

REMARKS OR REVISED DESCRIPTION:
The mark is in good condition. The bench mark is located on the corner of a concrete building. The mark is a brass nail driven into the concrete. The mark is located in the center of the building. The mark is located in the center of the building. The mark is located in the center of the building.

SUBMITTED BY D. J. Gruber DATE April 1983
TITLE Carto. 100.
AGENCY _____

Marks found in good condition need not be reported. **FILL IN ALL AVAILABLE INFORMATION**

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE Arizona COUNTY Yuma QUADRANGLE 4000

QUOTE PRIMARY REFERENCE _____
(Direction and distance)

DESIGNATION { LISTED _____
STAMPED _____ TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
Long. _____ ° _____ ' _____ " Disturbed
Elev. _____ feet Destroyed ESTABLISHED BY
Not Found USGS USBR
USC&GS State GS
USNPS USNFS
USGLO } (Other)
USBLM }

REMARKS OR REVISED DESCRIPTION:
The mark is in the area described has not been relocated, but has been elevated and made wider. The description of the bench mark would place it on the shoulder of the hwy. between the pavement and the barrow ditch. There is no question but what the post and tablet has been destroyed.

SUBMITTED BY D. J. Gruber DATE April 1983
TITLE Carto. 100.
AGENCY _____

Marks found in good condition need not be reported. **FILL IN ALL AVAILABLE INFORMATION**

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

Sufford

STATE ARIZONA COUNTY SUFORD QUADRANGLE 54-1000 (Qd 113)
 QUOTE PRIMARY REFERENCE Station 13 mi. southeast of
 (Direction and distance)

DESIGNATION { LISTED 1-70
 STAMPED 1-70 1000 TYPE OF MARK: BM x TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
 Long. _____ ° _____ ' _____ " Disturbed
 Elev. _____ feet Destroyed USGS ESTABLISHED BY
 Not Found USC&GS USBR
 USNPS State GS
 USGLO } USNFS
 USBLM } (Other)

REMARKS OR REVISED DESCRIPTION:

[Faint, illegible handwritten remarks]

SUBMITTED BY D. A. Gruben DATE April 1983
 TITLE Carto. Inc.
 AGENCY _____

Marks found in good condition need not be reported.
 GPO 16-54252-6 **FILL IN ALL AVAILABLE INFORMATION**

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

113

STATE ARIZONA COUNTY SUFORD QUADRANGLE 54-1000
 QUOTE PRIMARY REFERENCE Station 13 mi. southeast of
 (Direction and distance)

DESIGNATION { LISTED _____
 STAMPED 1-70 1000 TYPE OF MARK: BM x TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ " CONDITION
 Long. _____ ° _____ ' _____ " Disturbed
 Elev. 227.015 feet Destroyed USGS ESTABLISHED BY
 Not Found USC&GS USBR
 USNPS State GS
 USGLO } USNFS
 USBLM } (Other)

REMARKS OR REVISED DESCRIPTION:

The marker of the tablet is still embedded in the headwall of the concrete culvert, but the tablet has been chiseled off.

SUBMITTED BY D. A. Gruben DATE April 1983
 TITLE Carto. Inc.
 AGENCY USGS

Marks found in good condition need not be reported.
 GPO 16-54252-6 **FILL IN ALL AVAILABLE INFORMATION**

Please prepare in triplicate.

113

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

STATE Arizona COUNTY Coconino QUADRANGLE Coconino

QUOTE PRIMARY REFERENCE Coconino, 1.3 mi. north of
 (Direction and distance)

DESIGNATION { LISTED 5 226
 STAMPED 5 226 1542 TYPE OF MARK: BM x TT _____ TRIANG. _____

Lat. _____° _____' _____"	CONDITION	ESTABLISHED BY
Long. _____° _____' _____"	Disturbed <input type="checkbox"/>	USGS <input type="checkbox"/> USBR <input type="checkbox"/>
Elev. <u>7542.333</u> feet	Destroyed <input checked="" type="checkbox"/>	USC&GS <input type="checkbox"/> State GS <input type="checkbox"/>
	Not Found <input type="checkbox"/>	USNPS <input type="checkbox"/> USNFS <input type="checkbox"/>
		USGLO <input type="checkbox"/> (Other) <input type="checkbox"/>
		USBLM <input type="checkbox"/>

REMARKS OR REVISED DESCRIPTION:

The entire concrete monument is unprotected and the tablet has also been removed.

SUBMITTED BY W. G. ...
 TITLE Coconino
 AGENCY ...

DATE March 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE Arizona COUNTY Graham QUADRANGLE Safford

QUOTE PRIMARY REFERENCE At Soloman railroad station.
(Direction and distance)

DESIGNATION { LISTED 2979 (USGS)
STAMPED 2978.406 PHNX TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ "	CONDITION	USGS	ESTABLISHED BY	USBR	
Long. _____ ° _____ ' _____ "	Disturbed <input type="checkbox"/>	USC&GS	<input checked="" type="checkbox"/>	State GS	<input type="checkbox"/>
Elev. <u>2978.472</u> feet	Destroyed <input checked="" type="checkbox"/>	USNPS	<input type="checkbox"/>	USNFS	<input type="checkbox"/>
	Not Found <input type="checkbox"/>	USGLO	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
		USBLM			

REMARKS OR REVISED DESCRIPTION:

The station and the siding at the area has been removed and the ground leveled and graded. The area 150 ft west of the station site is under cultivation. No trace of the iron pipe or the cap could be found and it is considered to be destroyed.

SUBMITTED BY D.R. Gruben
TITLE Carto. Tec.
AGENCY USGS

DATE March 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE Arizona COUNTY Graham QUADRANGLE Safford

QUOTE PRIMARY REFERENCE Soloman Station, 2.5 miles southeast of.
(Direction and distance)

DESIGNATION { LISTED T-14
STAMPED 3030.939 TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____ ° _____ ' _____ "	CONDITION	USGS	ESTABLISHED BY	USBR	
Long. _____ ° _____ ' _____ "	Disturbed <input type="checkbox"/>	USC&GS	<input type="checkbox"/>	State GS	<input type="checkbox"/>
Elev. <u>3030.939</u> feet	Destroyed <input type="checkbox"/>	USNPS	<input type="checkbox"/>	USNFS	<input type="checkbox"/>
	Not Found <input checked="" type="checkbox"/>	USGLO	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
		USBLM			

REMARKS OR REVISED DESCRIPTION:

A considerable amount of earth has been removed from the area described to repair the erosion along the tracks and around the trestle. No trace of the bench mark was recovered and it is assumed it has been either destroyed or covered over.

SUBMITTED BY D.R. Gruben
TITLE Carto. Tec.
AGENCY USGS

DATE March 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE Arizona COUNTY Graham QUADRANGLE NK San Jose

QUOTE PRIMARY REFERENCE Solomon, 5.1 miles southeast of.
(Direction and distance)

DESIGNATION { LISTED 3195 PHIX
STAMPED 3195 Phix TYPE OF MARK: BM X TT _____ TRIANG. _____

Lat. _____° _____' _____"	CONDITION	ESTABLISHED BY
Long. _____° _____' _____"	Disturbed <input type="checkbox"/>	USGS <input checked="" type="checkbox"/> USBR <input type="checkbox"/>
Elev. <u>3194.916</u> feet	Destroyed <input type="checkbox"/>	USC&GS <input type="checkbox"/> State GS <input type="checkbox"/>
	Not Found <input type="checkbox"/>	USNPS <input type="checkbox"/> USNFS <input type="checkbox"/>
		USGLO <input type="checkbox"/> (Other) <input type="checkbox"/>
		USBLM <input type="checkbox"/>

REMARKS OR REVISED DESCRIPTION:

From the post office at Solomon, go 5.1 mi. east along hwys 70 and 666 to the forks where 70 and 666 divide and the end of truck travel. Continue on foot, in an southeasterly direction for approximately 0.8 mi. to the north bank of San Jose Wash. 0.25 mi. west of large drain fork, at a cut in the bank where old road crossed the wash. 112 ft. west of wash, 16 ft. north of trail, a 3 in pipe projecting 0.8 ft. with brass cap riveted to top. Stamped USGS 3195 PHIX

SUBMITTED BY D. R. Gruben
TITLE Carto. Rec.
AGENCY USGS NND

DATE April 1983

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.