

REPORT ON CONDITION OF SURVEY MARK

QUADRANGLE REPORT

STATE Ill COUNTY Ill QUAD NAME 30 116 33 301
STATION NAME and/or NUMBER H 661 QUAD NUMBER 30 116 33 (301)
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1943 Line 102
ELEVATION -235.114 ft./meter By: USGS NGS OTHER _____ (Name of agency)
CONDITION Degraded MARK STAMPED _____

REMARKS or REVISED DESCRIPTION Concrete post found abandoned metal one.
Wooden witness post found in good condition.

SUBMITTED BY W. S. Pinsky AGENCY U.S. Geological Survey DATE 03/03/1970

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178